

10008853

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,677,179 B2
DATED : January 13, 2004
INVENTOR(S) : Wusheng Yin et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page, Item [54] and Column 1, lines 1 and 2,


Title, "METHOD OF APPLYING NO-FLOW UNDERFILL" should read
-- **METHOD OF APPLYING FILLED NO-FLOW UNDERFILL** --; and

Column 6.

Line 47, "cu ring" should read -- curing --.

Signed and Sealed this

Seventh Day of December, 2004



JON W. DUDAS
Director of the United States Patent and Trademark Office